

Fitting M4 bolts to the aileron control

The 4 rivets R104 in diagram 338 A have to be replaced by 2 M4 bolts and nuts

