

Changing the lower corner cabin tubes

The lower corner cabin tubes 353289 need to be replaced with the ones provided in the kit.

