

Changing undercarriage safety cables

The safety cables 347258 in the diagram below need to be replaced with the ones provided, 2 on each arm.

